

UNDERWATER BRIDGE INSPECTION REPORT

STRUCTURE NO. 40508

1ST STREET

OVER THE

CANNON RIVER

DISTRICT 7 – LE SUEUR COUNTY



PREPARED FOR THE
MINNESOTA DEPARTMENT OF TRANSPORTATION

BY
COLLINS ENGINEERS, INC.

JOB NO. 5221

MINNESOTA DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION

REPORT SUMMARY:

The substructure units inspected below water at Bridge No. 40508, Center Pier, was found to be in good condition with coating failure from the bottom of the cap to the channel bottom over 50 percent of the surface area of the piles. The channel bottom around the substructure units appeared stable with no significant scour or debris accumulations.

INSPECTION FINDINGS:


- (A) The steel piles from the waterline to the channel bottom exhibited 1/8 to 1/4 inch diameter rust nodules over 10 percent of surface area, and 50 percent of coating loss and pitting (minimal with less than 1/32 inch depth) from bottom of the cap to channel bottom.

RECOMMENDATIONS:

- (A) Reinspect the submerged substructure units at the normal maximum recommended (NBIS) interval of five (5) years.

I hereby certify that this plan, specification, or report was prepared by me or under my direct supervision and that I am a duly Licensed Professional Engineer under the laws of the State of Minnesota.


Daniel G. Stromberg



Date 6/30/2008 Registration No. 21491

Respectfully submitted,

COLLINS ENGINEERS, INC.



Daniel G. Stromberg
Registered Professional
Engineer, State of Minnesota

MINNESOTA DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION

1. BRIDGE DATA

Bridge Number: 40508

Feature Crossed: Cannon River

Feature Carried: 1st Street

Location: District 7 – Le Sueur County

Bridge Description: The superstructure consists of two spans of multiple concrete beams.
The superstructure is supported by two reinforced concrete abutments and one steel pipe pile bent pier.

2. INSPECTION DATA

Professional Engineer/Team Leader: Daniel G. Stromberg, P.E., S.E.

Dive Team: Clayton G. Brookins, Valerie Roustan

Date: November 20, 2007

Weather Conditions: Cloudy, 48°F

Underwater Visibility: 1.0 foot

Waterway Velocity: Negligible / None

3. SUBSTRUCTURE INSPECTION DATA

Substructure Inspected: Center Pier.

General Shape: Center Pier consists of a single line of eleven steel pipe piles supporting a reinforced concrete cap.

Maximum Water Depth at Substructure Inspected: Approximately 4.6 feet.

4. WATERLINE DATUM

Water Level Reference: The top of the pier cap at the west end of Center Pier.

Water Surface: The waterline was approximately 6.1 feet below reference.
Waterline Elevation = 998.8.

5. NBIS CODING INFORMATION (Minnesota specific codes are used for 92B and 113)

Item 60: Substructure: Code 7

Item 61: Channel and Channel Protection: Code 8

Item 92B: Underwater Inspection: Code B/11/07

Item 113: Scour Critical Bridges: Code F/07

Bridge is scour critical because abutment or pier foundation is rated as unstable due to observed scour at bridge site.


 Yes X No




Photograph 1. Overall View of Structure, Looking Northeast.




Photograph 2. View of Center Pier, Looking Southwest.





UPSTREAM FASCIA PROFILE



DOWNSTREAM FASCIA PROFILE

Note:
Refer to Figure 1 for General Notes.

MINNESOTA DEPARTMENT OF TRANSPORTATION UNDERWATER BRIDGE INSPECTION		
STRUCTURE NO. 40508 OVER THE CANNON RIVER DISTRICT 7, LE SUEUR COUNTY, CITY OF MONTEVIDEO UPSTREAM AND DOWNSTREAM FASCIA PROFILES		
Drawn By: PRH	COLLINS ENGINEERS <small>123 North Wacker Drive Suite 300 Chicago, IL 60606 (312) 704-9300 www.collinsengr.com</small>	Date: NOV., 2007
Checked By: MDK		Scale: 1"=10'
Code: 522140508		Figure No.: 2

MINNESOTA DEPARTMENT OF TRANSPORTATION
OFFICE OF BRIDGES AND STRUCTURES
DAILY DIVING REPORT

INSPECTORS: Collins Engineers, Inc. DATE: November 20, 2007

ON-SITE TEAM LEADER: Daniel G. Stromberg, P.E., S.E.

BRIDGE NO: 40508 WEATHER: Cloudy, 48°F

WATERWAY CROSSED: Cannon River

DIVING OPERATION: X SCUBA SURFACE SUPPLIED AIR
 OTHER

PERSONNEL: Clayton G. Brookins, Valerie Roustan

EQUIPMENT: Scuba, U/W Light, Scraper, Lead Line, Sounding Pole, Probe Rod, Camera

TIME IN WATER: 10:00 a.m.

TIME OUT OF WATER: 10:20 a.m.

WATERWAY DATA: VELOCITY Negligible / None

VISIBILITY 1.0 foot

DEPTH 4.6 feet maximum at Center Pier

ELEMENTS INSPECTED: Center Pier.

REMARKS: Overall, the submerged steel of the piles was in good condition with no significant deterioration. The steel piles from the waterline to the channel bottom exhibited 1/8 to 1/4 inch diameter rust nodules over 10 percent of surface area, and 50 percent of coating loss and pitting (minimal with up to 1/32 inch penetration) from bottom of the cap to channel bottom. No notable channel bottom deficiencies were encountered.

FURTHER ACTION NEEDED: YES X NO

Reinspect the submerged substructure units at the normal maximum recommended (NBIS) interval of five (5) years.

MINNESOTA DEPARTMENT OF TRANSPORTATION
OFFICE OF BRIDGES AND STRUCTURES

UNDERWATER INSPECTION CONDITION RATING FORM

BRIDGE NO. 40508
INSPECTORS Collins Engineers, Inc.
ON-SITE TEAM LEADER Daniel G. Stromberg, P.E., S.E.
WATERWAY CROSSED Cannon River

INSPECTION DATE November 20, 2007
NOTE: USE ALL APPLICABLE CONDITION
DEFINITIONS AS DEFINED IN THE MINNESOTA
RECORDING AND CODING GUIDE INCLUDING
GENERAL, SUBSTRUCTURE, CHANNEL AND
PROTECTION, AND CULVERTS AND WALL
DEFINITIONS TO COMPLETE THIS FORM.

CONDITION RATING

UNIT REFERENCE NO.	UNIT DESCRIPTION	MAXIMUM DEPTH OF WATER	SUBSTRUCTURE						CHANNEL					GENERAL					
			PILING	COLUMNS, SHAFTS, OR FACES*	FOOTINGS	DISPLACEMENT	OTHER	OVERALL SUBSTRUCTURE CONDITION CODE*	SCOUR	EMBANKMENT EROSION	EMBANKMENT PROTECTION	OTHER (DRIFT/DEBRIS)	OVERALL CHANNEL & PROTECTION CONDITION	CONCRETE	STEEL	TIMBER	LOSS OF SECTION	PREVIOUS REPAIR OR MAINTENANCE	OTHER
		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
	Center Pier	4.6'	7	N	N	9	N	7	8	N	N	N	8	N	7	N	7	N	N

*UNDERWATER PORTION ONLY

REMARKS: Overall, the submerged steel of the piles was in good condition with no significant deterioration. The steel piles from the waterline to the channel bottom exhibited 1/8 to 1/4 inch diameter rust nodules over 10 percent of surface area, and 50 percent of coating loss and pitting (minimal with up to 1/32 inch penetration) from bottom of the cap to channel bottom. No notable channel bottom deficiencies were encountered.

NOTES: ATTACH SKETCHES AS NEEDED, IDENTIFY REMARK BY REFERRING TO UNIT REFERENCE NO. AND REMARK NO.
USE GENERAL SECTION TO IDENTIFY OVERALL PRESENCE OF SPALLS, CRACKS, CORROSION, ETC.